
Her/016/032

0021



Dianne R. Nielson, Ph.D.

Division Director

State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340

May 28, 1991

Mr. Ira Hatch Manti-LaSal National Forest Price Ranger District 599 West Price River Drive Price, Utah 84501

Dear Mr. Hatch:

Re: <u>ECFUTA Buried Telephone Cable to Service Crandall Canyon Mine</u>

The Division of Oil, Gas and Mining has reviewed the scoping document for the above-referenced project. A buried telephone cable would be addressed in the same manner as any other utility corridor crossing through the mine permit area. Utah coal mining regulation R614-301-521.161 requires the mine to clearly show all utility corridors on the permit area maps.

The Division would require Genwal Coal Company to amend the mine permit area map to show the telephone cable corridor.

Thank you for the opportunity to provide comment.

Sincerely,

Daron R. Haddock Permit Supervisor

a Haddale

mbm BTECFUTA.LTR